


© Without Target Running without Slope Speed-change (PLSV) – servo motor

◆Diagram:



◆Wiring:

