

力扬电机工业有限公司
J系列功能表

功能 \ 機種	J2n32MR(T)	J22A32MT	J24A32MT	J22A30ML	J24A28ML	J3n32MR(T)	J32A32MT	J34A32MT	J32A30ML	J34A28ML	J32B32MT	J34B32MT	J32B30ML	J34B28ML
程式容量 steps	16K	16k	16k	16k	16k	64k	64k	64k	64k	64k	64k	64k	64k	64k
单相高速计数器	8点(100KHz)	6点(100KHz)	6点(100KHz)	6点(100KHz)	6点(100KHz)	8点(200KHz)	8点(200KHz)	8点(200KHz)	8点(200KHz)	8点(200KHz)	8点(200KHz)	8点(200KHz)	8点(200KHz)	8点(200KHz)
AB相高速计数器	4组(100KHz)	3组(100KHz)	3组(100KHz)	3组(100KHz)	3组(100KHz)	4组(200KHz)	4组(200KHz)	4组(200KHz)	4组(200KHz)	4组(200KHz)	4组(200KHz)	4组(200KHz)	4组(200KHz)	4组(200KHz)
高速脉波输出	2Kpps	2点(100Kpps)	4点(100Kpps)	2点(400Kpps)	4点(400Kpps)	2Kpps	2点(200Kpps)	4点(200Kpps)	2点(400Kpps)	4点(400Kpps)	2点(200Kpps)	4点(200Kpps)	2点(400Kpps)	4点(400Kpps)
高速PWM / 0.01ms	X	2点	2点	2点	2点	X	2点	4点	2点	4点	2点	4点	2点	4点
任意频率输出	X	0	0	0	0	X	0	0	0	0	0	0	0	0
实时变速度功能	X	X	X	X	X	X	0	0	0	0	0	0	0	0
实时变位置功能	X	0	0	0	0	X	0	0	0	0	0	0	0	0
虚拟轴	X	1	1	1	1	X	1	2	1	2	1	2	1	2
浮点运算&三角函数	0	0	0	0	0	0	0	0	0	0	0	0	0	0
直线圆弧补间	X	X	X	X	X	X	X	X	X	X	0	0	0	0
手摇轮MPG	X	0	0	0	0	X	0	0	0	0	0	0	0	0
G00一段位置	X	0	0	0	0	X	0	0	0	0	0	0	0	0
G01直线补间	X	X	X	X	X	X	X	X	X	X	0	0	0	0
G02圆弧补间(CW)	X	X	X	X	X	X	X	X	X	X	0	0	0	0
G03圆弧补间(CCW)	X	X	X	X	X	X	X	X	X	X	0	0	0	0
G04电子凸轮	X	X	X	X	X	X	0	0	0	0	0	0	0	0
G05区间运动	X	X	X	X	X	X	X	X	X	X	0	0	0	0
G06比例跟随	X	0	0	0	0	X	0	0	0	0	0	0	0	0
G07飞剪运动	X	X	X	X	X	X	X	X	X	X	0	0	0	0
G08追剪运动	X	X	X	X	X	X	X	X	X	X	0	0	0	0
G28原点复归	X	0	0	0	0	X	0	0	0	0	0	0	0	0
对标功能														
输入倍波功能														
脉波输出方式	OC	OC	OC	LD	LD	OC	OC	OC	LD	LD	OC	OC	LD	LD

*** 脉波输出方式 OC(Open Collector) LD(Line Drive)(Differential)

*** 高速PWM 解析度为0.01ms