


© LYPLC Ex1n/1s MT type and Mitsubishi J2S servo wiring diagram
For use of Ex1n, 1s power supply (24vdc)



P3 : 512, CMX
P4 : 125, CDV
2000 PPS / 1 Rev